



Fig. 1






Fig. 2






Fig. 3






Fig. 4






Fig. 5






Fig. 6A




Fig. 6B




Fig. 6C




Fig. 6D








Fig. 7A



B (Non-crystalline portion) A (Crystalline portion)


Fig. 7B



After elongated at 70 to 80°C A

Fig. 7C

Not less than glass transition point
(non-crystalline portion melts)



A Deform

Fig. 7D

Not less than melting point
(crystalline portion melts)






Fig. 8






Fig. 9






Fig. 10






Fig. 11

